

Product Data



908 LENOIR ROAD • POST OFFICE BOX 1809
HICKORY, NORTH CAROLINA • 28603-1809
TELEPHONE (828) 328-1721
TOLL FREE (800) 334-5975
FAX (828) 328-4572

I-0510 Wax Solution

I-0510 Wax Solution can be added to a resin or a gel coat to enhance air drying of the air-exposed surface which, in turn, will reduce or eliminate the surface tackiness, thereby permitting sanding or grinding without plugging the sandpaper or grinding disc.

I-0510 is a solution of a film-former in Styrene Monomer and will mix readily with either a resin or a gel coat. We recommend adding I-0510 at the level of 5.0 – 10.0% by weight of the resin or gel coat. Mix thoroughly to completely distribute the film-former and apply in the usual manner.

It is important to remember that adhesion directly to the surface of a material containing I-0510 will be significantly decreased. It is imperative that this surface be sanded to remove this film before applying any additional layers of laminate to that surface.

PRECAUTION: I-0510 can phase out of solution in cold weather. Care should be taken to store containers of this product at 70°F. or higher and be sure to mix all containers thoroughly before using. I-0510 should be a clear liquid. If it is not, please consult our laboratories for advice.

page 1 of 1
HKR064-032706rev